



A. Rabette S. Sell

(Please Print)

/atchman

Hunt Valley

Luther Villa

~~191750~~ /
1917950[illegible]

Item	COMMENTS
------	----------

No New Defects Noted in Area

Were Switch in the area of Inspected Yes ☒ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?

Yes NO ✓

SPECIAL INSPECTION Yes NO ✓

Reason for special inspection ? _____

Track Inspector Signature

Carla R. Latta

Supervisory Certification

Paul Bayne



Page 1 of 1

W.O Number 1919027

To LINTHICUM

[illegible]

Supervisory Certification

T Schisler



Supervisory Certification MS
5-13-15

Page of

atchman

W.O Number 1919686 /

Inspected From Perr

To _____

[illegible]

Item	COMMENTS
------	----------

No New Defects Noted in Area

Were Switch in the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes NO ✓

SPECIAL INSPECTION Yes NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

Arthur Ricketts

Supervisory Certification

5-13-15

Page of

W.O Number 191 9030 /

To Bw 1

Item	COMMENTS
------	----------

Were Switch in the area of Inspected Yes VISUALLY NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?

Yes _____ NO ☒


SPECIAL INSPECTION Yes ☐ NO ☒

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

John Lee

Supervisory Certification 
5-14-15

OK

To Crom

Supervisory Certification

10

Page / of /

W.O Number 1917955 /

To LUTHERVILLE

[illegible]

5-14-15

OK

Page of

W.O Number 19129471

[illegible]

5-15-15

TRACK INSPECTION REPORTING FORM

Name Billard Date 5-14-2015 Page 1 of 2
 (Please Print)
 Watchman _____ W.O Number 1917922
 Inspected From Coltsprings To Camden yards

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	<u>Riding inspection</u>
	<u>Track inspection complete</u>
	<u>No new defects noted</u>

Were Switch in the area of Inspected Yes _____ NO _____

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 Yes _____ NO _____

SPECIAL INSPECTION Yes _____ NO _____

Reason for special Inspection ? _____

Track Inspector Signature

[Signature]

Supervisory Certification

[Signature]
5-15-15



B. Howard
(Please Print)

5-14-2015

Page 2 of 2

Pennix

W.O Number 1917922

To _____

[illegible]

Were Switch in the area of Inspected Yes _____ NO _____

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
Yes _____ NO _____

SPECIAL INSPECTION Yes_____ NO_____

Reason for special Inspection ? _____

Track Inspector Signature

Supervisory Certification

5-15-15

Page 1 of 2

W.O Number 1917998

To Cremwell

[illegible]

Supervisory Certification

Walter W. Bryant

5-18-75

Page 2 of 2

LIME

W.O Number

19,7998

[illegible]

Supervisory Certification

Walter W. B. Junt

5-18-15

10

Page of

Watchman

W.O Number 1997878

To Cold Spring

Item	Comments
	RIDING INSPECTION NO NEW DEFECTS NOTED IN AREA
LUTHERVILLE	91° 10:30 A
N. AVE	105° 12:30 P

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☐ NO ☒

SPECIAL INSPECTION Yes NO ☒

Reason for special Inspection ? _____

Str. Lee

Supervisory Certification

7-16-15

(Please Print)

Inspected From Lander

Lithium

W.O Number 19255431


[illegible]

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

SPECIAL INSPECTION Yes NO —

Reason for special Inspection ? _____

On the Roulette

isory Cretification 
5-18-15